

● PRINTER RUSH ●  
(PTO ASSISTANCE)

Application: 10/627944 Examiner: Palmer GAU: 2874

From: PAO Location: IDC FMF FDC Date: 4/15/05

Tracking #: 06046467 Week Date: 1/17/05

DOC CODE	DOC DATE	MISCELLANEOUS
<input type="checkbox"/> 1449	_____	<input type="checkbox"/> Continuing Data
<input type="checkbox"/> IDS	_____	<input type="checkbox"/> Foreign Priority
<input type="checkbox"/> CLM	_____	<input type="checkbox"/> Document Legibility
<input type="checkbox"/> IIFW	_____	<input type="checkbox"/> Fees
<input type="checkbox"/> SRFW	_____	<input type="checkbox"/> Other
<input type="checkbox"/> DRW	_____	
<input type="checkbox"/> OATH	_____	
<input type="checkbox"/> 312	_____	
<input type="checkbox"/> SPEC	_____	

Attention: Chief Drafts person

[RUSH] MESSAGE: please supply new drawing sheets -  
line through drawings caused by scanning.

Thank you.

[XRUSH] RESPONSE: (see ATTACHMENT)


CORRECTED DWGS OK.

INITIALS: SZ


NOTE: This form will be included as part of the official USPTO record, with the Response document coded as XRUSH.

REV 10/04


**Fig.1**




**Fig.2**




**Fig.3(a)**




**Fig.3(b)**




**Fig.4**




**Fig.5**







**Fig.6(a)**



**Fig.6(b)**




**Fig.6(c)**




**Fig.7**

(Light Intensity)




**Fig.8**


(Light Intensity)




**Fig.9**



**Fig.10**



**Fig.11 (a)**



**Fig.11 (b)**




Fig.12




Fig.13(a)







Fig.13(b)




**Fig.14**




**Fig.15(a)**




**Fig.15(b)**




**Fig.16(a) Fig.16(b) Fig.16(c)**




**Fig.17(a) Fig.17(b)**




**Fig.18(a)**




**Fig.18(b)**



**Fig.19(a)**




**Fig.19(b)**




Y  
↑  
Z → X

**Fig. 20 (a)**




**Fig. 20 (b)**




Y  
↑  
Z → X


**Fig. 21 (a)**




**Fig. 21 (b)**




**Fig.22**




**Fig.23**




**Fig.24**




**Fig.25**




**Fig.26**




**Fig.27 (a)**




**Fig.27 (b)**



**Fig.27 (c)**




**Fig.27 (d)**




**Fig.28 (a)**

(Light Intensity)




**Fig.28 (b)**


(Light Intensity)




**Fig.29 (a)**




**Fig.29 (b)**




**Fig.30 (a)**



**Fig.30 (b)**



**Fig. 31**



**Fig. 32**

